CORNER RECORD

Agency Index BK 23, PG 44

Document Number 20200088

Placer , California

Mission Hills Unit No. 2, Bk. L of Maps, Pg. 44

City of Rocklin County of Brief Legal Description Center radius point Rio Court, Mission Hills Unit No. 2, Bk. L of Maps, Pg. 44 **COORDINATES (Optional) CORNER TYPE** Se 18 Government Corner X Control Elevation Metric U.S. Survey Foot Meander Property Units Rancho Other Horizontal Datum X Zone Epoch Date Date of Survey October 16, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 T. 11 N., R. 7 E., M.D.B. & M. Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Other: **Pre-Construction** Left as found Established Rebuilt Corner/ Monument: Found and tagged Referenced Post-Construction Reestablished CORNER Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found railroad spike with punch (shown as 3/4" iron pipe) at the center radius point of Rio Court, as shown on Mission Hills Unit No. 2, Bk. L of Maps, Pg. 44 that could be damaged or destroyed by a proposed paving project. Monument was referenced as shown on page 2 of 2. The purpose of this RECORDS PACIE Corner Record is to preserve the location of the monument prior to construction. No attempt was made to determine the relationship between the monument and boundary lines. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 14, 2021 Exp. 12-31-2022 P.L.S. or R.C.E. No. *P.L.S.591* Signed **COUNTY SURVEYOR'S STATEMENT** JANUARY This Corner Record was received and examined and filed Signed

County Surveyor's Comment

